

Traill Cl.


Photo credit: Bonnie Halda State Historical Society

Date of photo: November 26, 1979

Location of negative: State Historical Society of North Dakota Liberty Memorial Building Bismarck, North Dakota 58505

West elevation and front (south) facade, looking NE

Photo 1 of 10



Trail CO.

Photo credit: Bonnie Halda State Historical Society

Date of photo: November 26, 2979

Location of negative: State Historical Society of North Dakota
Liberty Memorial Building

Bismarck, North Dakota 58505

East elevation, looking west

Photo 2 of 10



Truill CD.

Photo credit: Unknown Date of photo: ca. 1885

Location of negative: State Historical Society of North Dakota

Liberty Memorial Building Bismarck, North Dakota 58505

West elevation and front (south) facade, looking ENE

Photo 3 of 10



Traille Co.

Photo credit: Unknown Date of photo: Unknown

Location of negative: State Historical Society of North Dakota

Liberty Memorial Building

Bismarck, North Dakota 58505

West elevation and south (front) facade, looking NE

Photo 4 of 10



Traill CO.

Photo credit: Bonnie Halda

State Historical Society

Date of photo: November 26, 1979


Location of negative: State Historical Society of North Dakota

Liberty Memorial Building

Bismarck, North Dakota 58505

Foyer staircase on west wall across from livingroom, looking West.

Photo 5 of 10



Traill Co.

Photo credit: Bonnie Halda

State Historical Society

Date of photo: November 26, 1979

Location of negative: State Historical Society of North Dakota

Liberty Memorial Building Bismarck, North Dakota 58505

Parlor fireplace, east wall, looking east.

Photo 6 of 10



Traill co.

Photo credit: unknown Date of photo: unknown

Location of negative: State Historical Society of North Dakota

Liberty Memorial Building Bismarck, North Dakota 58505

NE corner of livingroom, looking NE

Photo 7 of 10



Photo credit: Unknown Photo Date: Unknown Location of negative:

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

East wall of livingroom, looking east.

Photo 8 of 20



Travill co.

Photo credit: Bonnie Halda

State Historical Society

Date of photo: November 26, 1979


Location of negative: State Historical Society of North Dakota

Liberty Memorial Building

Bismarck, North Dakota 58505

East wall of livingroom, looking east.

Photo 9 of 10



Iraill co.

Photo credit: unknown Date of photo: unknown

Location of negative: State Historical Society of North Dakota

Liberty Memorial Building

Bismarck, North Dakota 58505

SW corner of library/billiards addition, looking SW.

Photo 10 of 10



Photo credit: Un known Photo Date: Un known Location of negative:

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Livingroom looking south.

Photo 11 of 20



Photo credit: Unknown Photo Date: ca. 1900 Location of negative:

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

East elevation

Photo 12 of 20



Photo credit: Unknown Photo Date: ca. 1913

Location of negative:

Billiard room looking east.

Photo 13 of 20

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505



Photo credit: Un known Photo Date: ca. 1885

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center

Bismarck, ND 58505

South boundary of property.

Photo 14 of 20



Photo credit: Unknown
Photo Date: ca. 1920
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

West elevation and south (front) facade looking northeast.

Photo 15 of 20




Photo credit: Un known
Photo Date: Un known
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

South and west walls of bulliard room.

Photo 16 of 20



Photo credit: Un known
Photo Date: Un known
Location of negative: State Historical Society of North Da kota
North Da kota Heritage Center
Bismarck, ND 58505

Front stairway looking West.

Photo 17 of 20



Photo credit: Un known Photo Date: Un known Location of negative:

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Front stairway looking North.

Photo 18 of 20



Photo credit: Unknown
Photo Date: Unknown
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Parlor fireplace, east wall, looking east.

Photo 19 of 20



Photo credit: Un known Photo Date: Un known Location of negative:

State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Kitchen.

Photo 20 of 20